




Fine red dashed lines indicate selected fence and field lines where generally visible on aerial photographs. This information is unchecked. A portion of the northeast quarter of this quadrangle lies within a subsidence area. Vertical control based on latest available adjustments.



DMA 4048 | SE—SERIES V898

USGS
Historical File
Topographic Division

NOV 19 1979
1800